
Type	Gantry	L (mm)	L1 (mm)	C (mm)
1	60 - 90	530	351	238
2	100 - 130	720	471	378



Note
Insulator pins 5213 onw

When using insulator 5154,
order washer ø 17 / 50 x 3 A2
additionally.

Fasteners
Supplied complete with hook bolts.

Drawing number
567.00189, .00189-1

Ordering information
on gantry J 80
2353.1 Cross arm for feeder one-sided, on gantry beam