

Type	Gantry	L (mm)	L1 (mm)	C (mm)
1	60 - 90	530	351	238
2	100 - 130	720	471	378

Note

Insulator pins 5213 onw

When using insulator 5154,
order washer $\varnothing 17 / 50 \times 3$ A2
additionally.

Fasteners

Supplied complete with hook bolts.

Drawing number

567.00189, .00189-1

Ordering information

on gantry J 80

2353.1 Cross arm for feeder one-sided,
on gantry beam

