

Type	Gantry	L (mm)	L1 (mm)	C (mm)
1	60 - 90	800	740	238
2	100 - 130	1000	940	378

**Note**

Insulator pins 5213 o/w

When using insulator 5154,  
order washer  $\varnothing 17 / 50 \times 3$  A2  
additionally.

**Fasteners**

Supplied complete with hook bolts.

**Drawing number**

567.00190, .00190-1

**Ordering information**

on gantry J 120

2354.2 Cross arm for feeder two-sided,  
on gantry beam

