

Material

Fittings: Fe galvanized
Tube: Fe stainless

Type	L (mm)
06	600
08	800
10	1000
12	1250
15	1500
17	1750
20	2000
22	2250
25	2500

Note

Steady arm 5531 o/w
Clamp for steady arm 5515
Hinge clamp
for cross wire 5563

Drawing number

442.00021

Ordering information

Length 1000 mm
5523.10 Steady arm tube
with \varnothing 18 mm eye end fitting

