

Material

Fe-cast galvanized

Note

Supplied complete with U-bolts.

Associated parts

Steady arm 5527

Drawing number

353.00916

Ordering information*5454 Drop bracket for
steady arm on tube \varnothing 48 mm*