


**Material**

Cu

Type	t (mm)
1	1.5
2	2.0
3	3.0
4	4.0

**Note**

Insulator 5112 onw

**Drawing number**

412.00061

**Ordering information**

t = 3 mm

5518.3 Wedge insert for steady arm